



Type	Size	Model	HARDNESS		Code
			SOFT	HARD	
<i>E</i>	50x1030	OTK			0054.G0E
<i>U</i>	50x1030	OTK	[Blue bar representing hardness level]		0054.G0U
<i>C1</i>	50X1030	J3COMP	[Blue bar representing hardness level]		0301.C1
<i>Q</i>	50x1030	OTK	[Blue bar representing hardness level]		0054.G0Q
<i>N</i>	50x1030	OTK	[Blue bar representing hardness level]		0054.G0N
<i>C2</i>	50X1030	J3 COMP	[Blue bar representing hardness level]		0301.C2
<i>H</i>	50x1030	OTK	[Blue bar representing hardness level]		0054.G0H
<i>C3</i>	50X1030	J3 COMP	[Blue bar representing hardness level]		0301.C3
<i>HH</i>	50x1030	OTK	[Blue bar representing hardness level]		0054.G0HH
<i>U</i>	50x1030	OTK - KZ	[Blue bar representing hardness level]		0054.H0U
<i>Q</i>	50x1030	OTK-KZ	[Blue bar representing hardness level]		0054.H0Q
<i>N</i>	50x1030	OTK-KZ	[Blue bar representing hardness level]		0054.H0N
<i>H</i>	50x1030	OTK-KZ	[Blue bar representing hardness level]		0054.H0H
<i>HH</i>	50x1030	OTK-KZ	[Blue bar representing hardness level]		0054.H0HH